



159 Ort Lane
Merlin, OR, US 97532
Phone: + 1 541 471 6256
Fax: + 1 541 471 6251
www.linxtechnologies.com

April 16, 2014

To: All customers using MS Series Keyfob products

Re: Product change notice

Dear customer,

Linx Technologies is announcing a change in operation of the MS Series Keyfob products.

Once implemented product will no longer ship with a default address; a randomized address will be created as part of the production assembly and test process.

We are committed to working closely with our customers regarding this change. Please contact Linx Sales or Customer Service should you have any questions or concerns.

Product Change Notice for all MS Series Keyfob products

PCN #: LPCN-140416-2

Publish Date: April 16, 2014

Type of Change

Firmware operation change

Products Affected

- OTX-315-HH-KF1-MS
- OTX-315-HH-KF2-MS
- OTX-315-HH-KF3-MS
- OTX-315-HH-KF4-MS
- OTX-315-HH-KF5-MS
- OTX-418-HH-KF1-MS
- OTX-418-HH-KF2-MS
- OTX-418-HH-KF3-MS
- OTX-418-HH-KF4-MS
- OTX-418-HH-KF5-MS
- OTX-433-HH-KF1-MS
- OTX-433-HH-KF2-MS
- OTX-433-HH-KF3-MS
- OTX-433-HH-KF4-MS
- OTX-433-HH-KF5-MS

Description of Change

Firmware change to remove default addressing

Reason for Change

Eliminate the ability to deploy systems utilizing default addressing

Effect of Change

Form: No change

Fit: No change

Function: remove default addressing from device operation

Quality: No change

Anticipated First Ship Date

July 2014

Qualification Data

There is no change in form, fit, markings or part numbers

Last Time Buy Date

No formal last time buy date is established