



159 Ort Lane
Merlin, OR, US 97532
Phone: + 1 541 471 6256
Fax: + 1 541 471 6251
www.linxtechnologies.com

February 14, 2013

To: All customers using the TRM-433-LT Transceiver

Re: Product change notice

Dear customer,

Linx Technologies is announcing a change in one of the internal components in the TRM-433-LT Transceiver. The change only affects the 433 MHz version of the Transceiver, not the 418 MHz or 315 MHz version products.

Modules assembled with this part meet all published specification and production test parameters. There is no change in form, fit, markings or part numbers.

We are committed to working closely with our customers regarding this change. Please contact Linx Sales or Customer Service should you have any questions or concerns.

Product Change Notice for TRM-433-LT

PCN #: LPCN-130214-2

Publish Date: February 14, 2013

Type of Change

Internal component value and/or type change.

Products Affected

- TRM-433-LT

Description of Change

Change of internal part.

Reason for Change

Production yield improvement

Effect of Change

Form: No change

Fit: No change

Function: No change

Quality: No change

Radiated emission scans of representative product pre- and post-change show no deleterious effects; all operations are within FCC required limits.

Anticipated First Ship Date

Immediate, starting with lot code TX4023.

Qualification Data

Modules assembled with the part change meet all published specification and production test parameters. There is no change in form, fit, markings or part numbers.

Last Time Buy Date

No formal last time buy date is established.