



159 Ort Lane
Merlin, OR, US 97532
Phone: + 1 541 471 6256
Fax: + 1 541 471 6251
www.linxtechnologies.com

August 14, 2012

To: All customers using the CONSMA001

Re: Product change notice

Dear customer,

Linx Technologies is announcing a change in manufacturing location for the CONSMA001. Product from the new manufacturing location will replace the existing product offering.

The new product is mechanically identical to, and offers equivalent electrical performance, as the product from the current manufacturing location. The new manufacturing location eliminates supply chain impacts on product costs.

We are committed to working closely with our customers during the transition to address any questions or concerns. Materials from the existing manufacturing location will still be available under new part numbers.

Product Change Notice for CONSMA001

PCN #: LPCN-120814-1

Publish Date: August 14, 2012

Type of Change

Change in the manufacturing location for CONSMA001

Products Affected

- CONSMA001

Description of Change

The manufacturing location for the CONSMA001 is being changed. Summary electrical performance is provided in Table 1 below.

Current Manufacturing Location								
Sample No.	S11 [dB]				S21 [dB]			
	300 MHz	425 MHz	900 MHz	2.45 GHz	300 MHz	425 MHz	900 MHz	2.45 GHz
Average	-21.68	-19.05	-13.98	-21.97	-0.07	-0.10	-0.27	0.41
Std Dev	0.32	0.14	0.10	0.89	0.01	0.01	0.01	0.03
New Manufacturing Location								
Sample No.	S11 [dB]				S21 [dB]			
	300 MHz	425 MHz	900 MHz	2.45 GHz	300 MHz	425 MHz	900 MHz	2.45 GHz
Average	-21.65	-18.88	-14.10	-17.93	-0.07	-0.11	-0.27	0.49
Std Dev	0.81	0.60	0.64	0.81	0.01	0.01	0.03	0.04

Table 1:CONSMA001 Summary Validation Test Data

Reason for Change

Manufacturing consolidation and cost containment

Effect of Change

Form: No change

Fit: No change

Function: No change

Quality: No change



159 Ort Lane
Merlin, OR, US 97532
Phone: + 1 541 471 6256
Fax: + 1 541 471 6251
www.linxtechnologies.com

Anticipated First Ship Date

August 2012

Qualification Data

Qualification plan specifics are not for general release. Please contact Linx directly for additional information or assistance.

Last Time Buy Date

No formal last time buy date is established. Product from the new location will be supplied as existing inventory depletes.

Product from the current manufacturing location will still be available under the new part number CONSMA001.1.